

Vehicle History Report #: 48872016 Report Date: October 3, 2023 | 1:16 PM EDT

Report Status: Complete

### 2015 HYUNDAI ELANTRA SE

Sedan | 4 Cylinders | Gas KMHDH4AH7FU262648

Country of Assembly: Korea (South) Last Reported Odometer: 149,724 KM



**Accident/Damage Records Found** 



Last Registered In: Ontario (Normal)



9 Service Records Found



No U.S. History Found



3 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of October 03, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

## **Vehicle History Report**



INCIDENT DATE	DETAILS	AMOUNT
1 2017 Jul 22	Kanata, Ontario, Canada	
	Police Reported Accident: Accident reported: moderate damage	
	Involving front or side impact	
	with another motor vehicle	
	Damage to right rear	
	Estimate: Left Rear Side   Estimate Date: 2017 Jul 24	\$2,983.15
	Claim: Other Damage	\$3,398.00



# Registration

This vehicle has been registered in the province of Ontario in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



## Service Records

DATE	ODOMETER	SOURCE	DETAILS
2014 Sep 12		Hyundai on Hunt Club	Vehicle serviced
		Nepean, Ontario, Canada	<ul> <li>Pre-delivery inspection completed</li> </ul>
		•	Four tires mounted
2014 Nov 12	2,947 KM	Hyundai on Hunt Club	Vehicle serviced
		Nepean, Ontario, Canada	
2016 Aug 2	33,392 KM	Jiffy Lube #2872	Vehicle serviced
•		Mississauga, Ontario, Canada	Maintenance inspection completed
		<b>3</b> , , ,	Cabin air filter replaced/cleaned
			Oil and filter changed
			Engine oil system flushed
			Fluids checked
2017 Jun 9		Jiffy Lube #3516	Vehicle serviced
		Belleville, Ontario, Canada	Maintenance inspection completed
		, ,	Oil and filter changed
			Fluids checked
2021 Jan 22	113,966 KM	Great Canadian Oil Change	Vehicle serviced
		Stittsville, Ontario, Canada	Maintenance inspection completed
			Oil and filter changed
			Air filter checked
2022 Jan 15	131,199 KM	Great Canadian Oil Change	Vehicle serviced
		Stittsville, Ontario, Canada	<ul> <li>Maintenance inspection completed</li> </ul>
			Fluids checked
			Oil and filter changed
2022 Dec 8	145,253 KM	Great Canadian Oil Change	Vehicle serviced
		Stittsville, Ontario, Canada	Maintenance inspection completed
			Fluids checked
			Oil and filter changed
2023 Apr 17	149,724 KM	Great Canadian Oil Change	Vehicle serviced
· ·		Stittsville, Ontario, Canada	Maintenance inspection completed
		, , , , , , , , , , , , , , , , , , , ,	Fluids checked

	ODOMETER	SOURCE	DETAILS
			<ul><li>Oil and filter changed</li><li>Splash shield replaced/repaired</li></ul>
2023 Sep 28		Bean Chevrolet Buick GMC Ltd. Carleton Place, Ontario, Canada	Vehicle serviced  Oil and filter changed



### **Open Recalls**

Recall #: R0180 | Engine Control Module Reprogramming Recall Date: 2022 May 06

#### **Recall Description**

Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This only affects certain vehicles equipped with a 2.0 L Nu GDI engine. For the Sonata model, only the Sonata Hybrid and Plug-In Hybrid (PHEV) models are affected by this campaign. This is an expansion of R0180 (Transport Canada #2021-575). Any vehicle that received a software update under campaign R0180 does not require this update. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to update the software for the engine control module. Note: Hyundai recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Hyundai advises you to immediately visit a Hyundai dealership to have your vehicle diagnosed.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit **Hyundai's website**.

Recall #: C0525 - (UD/MD/JK) | Underbody Corrosion Recall Date: 2023 Mar 08

#### **Recall Description**

Issue: Hyundai Auto Canada is conducting a Special Service Campaign that provides anti-corrosion treatment to certain underbody components. Over time, components under the vehicle, including brake lines could corrode. In extreme cases, a brake line could fail and leak. A brake fluid leak can result in reduced braking. Safety Risk: Reduced braking can cause an extended stopping distance and increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect the underbody, including the brake lines. The dealer will apply an anti-corrosion treatment to certain parts, and replace the brake lines if necessary.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit Hyundai's website.

Recall #: R0246 | Anti-lock Brake System (ABS) Module (Interim - Recall Remedy Not Yet Available) Recall Date: 2023 Sep 22

#### **Recall Description**

Issue: On certain vehicles, brake fluid could leak into the control module for the antilock brake system (ABS) and cause it to short circuit. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai Canada will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse for the ABS module. Hyundai Canada recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit **Hyundai's website**.



### **Stolen Vehicle Check**

This vehicle is not actively declared stolen.



## **Detailed History**

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2014 Sep 12		Hyundai on Hunt Club Nepean, Ontario, Canada	Service Record	Vehicle serviced
2014 Sep 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Personal
2014 Nov 12	2,947 KM	Hyundai on Hunt Club Nepean, Ontario, Canada	Service Record	Vehicle serviced
2015 Jul 13		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2016 Jul 13		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2016 Aug 2	33,392 KM	Jiffy Lube #2872 Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2017 Jun 9		Jiffy Lube #3516 Belleville, Ontario, Canada	Service Record	Vehicle serviced
2017 Jul 20		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2017 Jul 22		Police Reported Accident Ontario, Canada	Police Report	Accident Reported:
2017 Jul 22		Insurance Records Ontario, Canada		
2017 Jul 22	53,926 KM	Insurance Records Kanata, Ontario, Canada	Estimate Repair	Estimate Date: 2017-07-24 Left Rear Side
2018 Mar 27		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2018 Sep 28	74,725 KM	Independent Source Ottawa, Ontario, Canada	Odometer reading	

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 Oct 17		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2019 Mar 7		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2021 Jan 22	113,966 KM	Great Canadian Oil Change Stittsville, Ontario, Canada	Service Record	Vehicle serviced
2021 Jul 8		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2022 Jan 15	131,199 KM	Great Canadian Oil Change Stittsville, Ontario, Canada	Service Record	Vehicle serviced
2022 May 6		HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0180
2022 Jun 26		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2022 Dec 8	145,253 KM	Great Canadian Oil Change Stittsville, Ontario, Canada	Service Record	Vehicle serviced
2023 Mar 8		HYUNDAI	Recall	Manufacturer Recall Issued Recall # C0525 - (UD/MD/JK)
2023 Apr 17	149,724 KM	Great Canadian Oil Change Stittsville, Ontario, Canada	Service Record	Vehicle serviced
2023 Sep 22		HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0246
2023 Sep 22		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2023 Sep 28		Bean Chevrolet Buick GMC Ltd. Carleton Place, Ontario, Canada	Service Record	Vehicle serviced



# Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantablity, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada. Conditions of Use and any CARFAX Canada and User License Agreements as each may be amended from time to time by CARFAX Canada. Conditions of Use

© 2023 CARFAX Canada ULC. All rights reserved.

