



## CLAIMS VEHICLE HISTORY REPORT

## VEHICLE DETAILS:

VIN: 3VWDL7AJ5DM263366  
 Year/Make/Model: 2013 VOLKSWAGEN JETTA  
 TDI  
 Body Style: SEDAN  
 Country of Assembly: Mexico  
 Cylinders: 4  
 Fuel Type: Diesel

## REPORT DETAILS:

Report Number: 29016684  
 Report Date: 7/14/2020 11:22 AM EST  
 Report Status: Complete

## REPORT SUMMARY

	<b>Accidents / Damage:</b>	No damage records found
	<b>Canadian Registration:</b>	Nova Scotia (Normal) Ontario (Normal)
	<b>Stolen Status:</b>	Not actively declared stolen
	<b>U.S. History:</b>	No U.S. history found
	<b>Recalls:</b>	1 recall notice(s) found
	<b>Service History:</b>	8 record(s) found

## QUESTIONS?

WE'RE HERE TO HELP.

CALL  
1.866.835.8612



EMAIL  
SUPPORT@CARFAX.CA



## Report Findings in Chronological Order

Below are all records for the vehicle, listed in the order that they occurred.

Date	Location	Data Source	Type of Record	Detail	Odometer
03/04/2013	Hebbville, Nova Scotia, Canada	Bridgewater VW	Service Record	Vehicle serviced	
09/27/2013	Hebbville, Nova Scotia, Canada	Bridgewater VW	Service Record	Vehicle serviced	
10/09/2013	Nova Scotia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
10/09/2013	Nova Scotia, Canada	Motor Vehicle Dept.	Canadian Renewal	First Owner Reported	
09/22/2015	Nova Scotia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
07/19/2018	Ottawa, Ontario, Canada	Independent Source	Odometer reading		123,800 KM
07/24/2018	Ontario, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
07/24/2018	Ontario, Canada	Motor Vehicle Dept.	Canadian Renewal	Dealer took title of this vehicle while it was in inventory	
07/26/2018	Pembroke, Ontario, Canada	Edwards Mazda	Service Record	Vehicle serviced	
07/31/2018	Ontario, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
07/31/2018	Ontario, Canada	Motor Vehicle Dept.	Canadian Renewal	New Owner Reported	
07/31/2018	Pembroke, Ontario, Canada	Edwards Mazda	Service Record	Vehicle serviced	123,854 KM
08/14/2018	Pembroke, Ontario, Canada	Edwards Mazda	Service Record	Vehicle serviced	129,087 KM
11/21/2018	Pembroke, Ontario, Canada	Edwards Mazda	Service Record	Vehicle serviced	133,341 KM
03/04/2019	Pembroke, Ontario, Canada	Edwards Mazda	Service Record	Vehicle serviced	136,875 KM
06/30/2019	Ontario, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	

Date	Location	Data Source	Type of Record	Detail	Odometer
06/30/2019	 Ontario, Canada	Motor Vehicle Dept.	Previous use	Commercial	
08/27/2019		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 37M2	
07/07/2020	 Pembroke, Ontario, Canada	Edwards Mazda	Service Record	Vehicle serviced	161,952 KM

## Accident, Collision and Damage Detail

If the vehicle has had any history of accidents, collisions or damage in either Canada or the U.S., the records are outlined in this section.

VIN: 3VWDL7AJ5DM263366

### Police Reported Accidents

Incident Date	Location	Detail
No police reported accidents found		

### Accident/Damage Estimates

Accident estimate records are generated by collision estimating facilities from the process of estimating the amount and extent of damage to a vehicle. Estimates in some cases have associated insurance claims.

Incident Date	Location	Estimate Date	Type of Record	Detail	Amount	Odometer
No estimates found						

### Insurance Claims

The insurance claims identified in this report do not include any medical pay-outs, damage to other vehicles, damage to property, towing, rental cars, or any other incidental damages.

Incident Date	Location	Type of Claim	Detail	Amount	Odometer
No claims found					

### Other Damage Records

Record Date	Location	Type of Record	Detail	Odometer
No other damage records found				

## Canadian Registration

This section details where in Canada the vehicle is now or has ever been registered, as well as the status (Inspection Required, Normal, Non-repairable, Rebuilt, Salvage, Stolen) of the vehicle in those jurisdictions.

Jurisdiction	Branding	Detail
Alberta	Not found	
British Columbia	Not found	
Manitoba	Not found	
New Brunswick	Not found	
Newfoundland	Not found	
<b>Nova Scotia</b>	<b>NORMAL</b>	This vehicle has been registered as Normal in this jurisdiction.
Northwest Territories	Not found	
Nunavut	Not found	
<b>Ontario</b>	<b>NORMAL</b>	This vehicle has been registered as Normal in this jurisdiction.
Prince Edward Island	Not found	
Quebec	Not found	
Saskatchewan	Not found	
Yukon Territories	Not found	

## Stolen Vehicle Check

This section outlines data from the Canadian Police Information Centre (CPIC), which is operated by the RCMP under the stewardship of National Police Services, on behalf of the Canadian law enforcement community.

#### Stolen Vehicle Check

Not declared stolen.

## Import Records

If the vehicle has been imported, you will find the details below.

#### Import Records

No vehicle import records found

## United States Vehicle History

In addition to information about the vehicle's history in Canada, CARFAX Canada also searches for information about the vehicle's history in the United States. If we discover any events in the U.S., you will find them below. Details about accidents, collisions and damage, or any import records will appear in the preceding sections of your report.

#### U.S. History Records

No U.S. history records found

## Recalls

#### Recall # 37M2

Recall Date: 8/27/2019

#### MICRO SWITCH

#### Recall Description:

Over time, a build up of silicate on the shift lever micro switch contacts can result in an isolation like layer that may be interpreted as an open micro switch. This open switch normally indicates that the shift lever is in P park position. If the build up happens, it may be possible to remove the key from the ignition switch without the shift lever being in the P park position because the system is unable to recognize that the vehicle is not in P park. This makes the vehicle noncompliant with FMVSS 114 Theft protection and rollaway prevention. If the ignition key is removed without the shift lever being in P Park position, there is a risk that the vehicle may roll away, resulting in a crash that could injure people and damage property.



#### Remedy

Install an additional switch and circuit board.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit Volkswagen's website.

## Service History

These are records of service performed on the vehicle. These are the records reported to CARFAX Canada when this report was run – it is possible that service has occurred that is not captured here.

Date	Address	Data Source	Type of Record	Detail	Odometer
03/04/2013	 Hebbville, Nova Scotia, Canada	Bridgewater VW	Service Record	Vehicle serviced Pre-delivery inspection completed Maintenance inspection completed Battery/charging system checked Paint protection applied Nitrogen fill tires Floor mats installed	
09/27/2013	 Hebbville, Nova Scotia, Canada	Bridgewater VW	Service Record	Vehicle serviced Maintenance inspection completed	
07/26/2018	 Pembroke, Ontario, Canada	Edwards Mazda	Service Record	Vehicle serviced Maintenance inspection completed A/C system checked Tire condition and pressure checked Front brake rotor(s) replaced	
07/31/2018	 Pembroke, Ontario, Canada	Edwards Mazda	Service Record	Vehicle serviced Vehicle washed/detailed	123,854 KM
08/14/2018	 Pembroke, Ontario, Canada	Edwards Mazda	Service Record	Vehicle serviced Heater core replaced	129,087 KM

Date	Address	Data Source	Type of Record	Detail	Odometer
11/21/2018	 Pembroke, Ontario, Canada	Edwards Mazda	Service Record	Vehicle serviced Tire condition and pressure checked	133,341 KM
03/04/2019	 Pembroke, Ontario, Canada	Edwards Mazda	Service Record	Vehicle serviced Tire condition and pressure checked	136,875 KM
07/07/2020	 Pembroke, Ontario, Canada	Edwards Mazda	Service Record	Vehicle serviced Maintenance inspection completed	161,952 KM



© Copyright 2005 - 2020 CARFAX Canada ULC. All rights reserved.

#### Information on Reports

#### Conditions of Use

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

**i** Please note CARPROOF recently changed its name to CARFAX Canada!