



Vehicle History Report #: 45446213
Report Date: April 17, 2023 | 6:54 PM EDT
Report Status: Complete

2011 NISSAN MURANO S

Sport utility vehicle | 6 Cylinders | Gas
JN8AZ1MW5BW176822
Country of Assembly: Japan
Last Reported Odometer: 114,065 KM



Accident/Damage Records Found



Last Registered In:
Québec (Normal)



9 Service Records Found



U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.
Visit us at support.carfax.ca




This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of April 17, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report




Accident/Damage

JN8AZ1MW5BW176822

INCIDENT DATE	DETAILS	AMOUNT
 2015 Sep 27	Orleans, Ontario, Canada	
	Estimate: Left Front Side Estimate Date: 2015 Sep 28 Claim: Unknown	\$1,445.44 \$1,500.00



Registration


 This vehicle has been registered in the following locations in **Canada** (listed oldest to newest):

- In the province of **Ontario** with **Normal** branding.
- In the province of **Québec** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
 2012 Mar 19	11,641 MI	Harbor Nissan Port Charlotte, Florida, United States	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Vehicle washed/detailed • Oil and filter changed
 2014 Jan 24		Sears Auto Center Port Charlotte, Florida, United States	Vehicle serviced <ul style="list-style-type: none"> • Tire(s) replaced • Tire pressure monitoring system serviced • Alignment performed • Tire(s) balanced
 2016 May 11		Davidson Nissan Watertown, New York, United States	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Oil and filter changed
 2016 Nov 2		Davidson Nissan Watertown, New York, United States	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Oil and filter changed • Tires rotated
 2017 Oct 18	105,115 MI	Davidson Nissan Watertown, New York, United States	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Oil and filter changed
 2017 Nov 1	105,839 MI	Davidson Nissan Watertown, New York, United States	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Engine checked • Wipers/washers checked • Wiper(s) replaced
2018 Jan 2		Roch Drouin Auto Repair Rockland, Ontario, Canada	Vehicle serviced
 2018 Apr 23	109,576 MI	Davidson Nissan Watertown, New York, United States	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Tires rotated • Oil and filter changed • Air filter replaced

JN8AZ1MW5BW17682Z

	ODOMETER	SOURCE	DETAILS
2018 Aug 13	114,065 KM	Great Canadian Oil Change Rockland, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Emissions system serviced



Open Recalls

Recall #: POA08 | MUR QST BRK FLD FLH NTB21047 Recall Date: 2021 May 27

Recall Description

A potential chemical reaction between the valve surface coating (Chromate layer) and the DOT3 brake fluid may cause a Gel to form around the normally closed (NC) valve. In some cases, it can cause the NC valve to be stuck open. The NC valve inside the ABS actuator may stick open and direct additional brake fluid flow to a reservoir inside the ABS actuator. As a result, the brake fluid pressure may fluctuate and the customer may experience increased brake pedal travel.

Remedy

All affected vehicles will have the brake fluid replaced (DOT3 to DOT4 fluid). Dealers will inspect the ABS actuator using Consult. If needed, the ABS actuator will be replaced. An owner s manual insert will be provided to customers with instruction to use DOT4 brake fluid to prevent the subject condition from reoccurring, and the brake fluid reservoir cap will be changed. This service, which is conducted at no charge to you for parts and labor, could take up to four and a half (4.5) hours to complete depending on the inspection results. However, your Nissan dealer may require your vehicle for a longer period of time based upon their work schedule or if the ABS actuator requires replacement.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit [Nissan's website](#).



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2011 Aug 15		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2012 Mar 19	11,641 MI	Harbor Nissan Port Charlotte, Florida, United States	Service Record	Vehicle serviced
2012 Aug 26		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Jan 24		Sears Auto Center Port Charlotte, Florida, United States	Service Record	Vehicle serviced
2014 Aug 26		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed

JN8AZ1MW5BW17682Z

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2015 Aug 26		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2015 Sep 27		Ontario, Canada	Unknown	
2015 Sep 27	81,803 KM	Insurance Records Orleans, Ontario, Canada	Estimate Repair	Estimate Date: 2015-09-28 Left Front Side
 2016 May 11		Davidson Nissan Watertown, New York, United States	Service Record	Vehicle serviced
2016 Aug 26		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
 2016 Nov 2		Davidson Nissan Watertown, New York, United States	Service Record	Vehicle serviced
2017 Aug 26		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
 2017 Oct 18	105,115 MI	Davidson Nissan Watertown, New York, United States	Service Record	Vehicle serviced
 2017 Nov 1	105,839 MI	Davidson Nissan Watertown, New York, United States	Service Record	Vehicle serviced
2018 Jan 2		Roch Drouin Auto Repair Rockland, Ontario, Canada	Service Record	Vehicle serviced
 2018 Apr 23	109,576 MI	Davidson Nissan Watertown, New York, United States	Service Record	Vehicle serviced
2018 Aug 13	114,065 KM	Great Canadian Oil Change Rockland, Ontario, Canada	Service Record	Vehicle serviced
2018 Aug 26		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Apr 10		Motor Vehicle Dept. Québec, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2019 Sep 11		Motor Vehicle Dept. Québec, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Sep 16		Motor Vehicle Dept. Québec, Canada	Canadian Renewal	Registration Issued or Renewed
2021 May 27		NISSAN	Recall	Manufacturer Recall Issued Recall # POA08

JN8AZ1MW5BW17682Z

ODOMETER	SOURCE	RECORD TYPE	DETAILS
2021 Sep 15	Motor Vehicle Dept. Québec, Canada	Canadian Renewal	Registration Issued or Renewed
2022 Sep 14	Motor Vehicle Dept. Québec, Canada	Canadian Renewal	Registration Issued or Renewed



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. [Conditions of Use](#)

© 2023 CARFAX Canada ULC. All rights reserved.

